Report from E1

Burkard 07/18/03

- •Hardware Status
- •Testing L1 \rightarrow L2 muon interface
- •Initial tests of XTRP interface


Hardware Status

Bad news: •Delay of new pulsar boards

until beginning of August

Delay of AUX cards

Good news: TAXI Rx production running smoothly



Firmware Adding in new features

- •Tx & Rx: HRR
- •Tx: sending multiple events
- •Rx: DAQ buffer fixed (MUON) & variable length (XTRP & Pulsar OUT)

Front End Readout code:

- "poor man" dump to screen
- "official": Software event builder is working

Since 03/07 New Crate in Trigger Room: LEVEL2_PULSAR_00 (b0l2pu00)

Setup:


- Muon & XTRP Tx → Muon & XTRP Rx
- Copy in TEST_LEVEL2_01

Methodology:

- extensive standalone test in test stand crate
- extensive standalone test in TrigRoom crate
- interface with real system

Testing L1 \rightarrow **L2 Muon interface:**


•LA:



- Screen dump OK
- •Record calib. and cosmic events in normal & Myron mode with SEVB \rightarrow Cheng-Ju

Initial Testing of XTRP interface with XTRP testpattern (this night)

•LA:



•Screen dump OK